

CITROEN

Model: C1 1,0 • Saxo 1,1/1,4/1,6 • C2 1,1/1,4/1,6 • C3/Pluriel 1,1/1,4/1,6
 Xsara 1,4/1,6/2,0 • Xsara Picasso 1,6/2,0 • C4 1,4/1,6/2,0
 C5 2,0/3,0 • C6 3,0 • Synergie 2,0 • C8 2,0/2,2/3,0
 Berlingo 1,1/1,4/1,6 • Dispatch 2,0 • Relay II 2,0

Engine management

Trouble code Identification

EOBD type	Fault location	Probable cause
PO, P2, UO	Refer to EOBD trouble code tables	-
P1110	Air conditioning (AC) - request signal	Wiring, multifunction control module, AC refrigerant pressure sensor
P1112	Throttle motor position sensor 1/2 - position check	Wiring, throttle motor position sensor 1/2, throttle motor
P1133	Throttle motor position sensor 1, manifold absolute pressure (MAP) sensor - correlation	Wiring, throttle motor position sensor 1, MAP sensor, throttle motor, mechanical fault
P1134	Throttle motor position sensor 2, manifold absolute pressure (MAP) sensor - correlation	Wiring, throttle motor position sensor 2, throttle motor, mechanical fault
P1135	Intake manifold	-
P1147	Camshaft position (CMP) actuator	Wiring, camshaft position (CMP) actuator, mechanical fault
P1148	Camshaft position (CMP) actuator	Wiring, camshaft position (CMP) actuator, mechanical fault
P1149	Camshaft position (CMP) actuator	Wiring, camshaft position (CMP) actuator, mechanical fault
P1150	Throttle motor - control	Wiring, throttle motor, throttle motor position sensor 1/2, accelerator pedal position (APR) sensor
P1151	Throttle motor - control	Wiring, throttle motor, throttle motor position sensor 1/2, accelerator pedal position (APP) sensor
P1152	Throttle motor position sensor 1/2 - correlation	Wiring, throttle motor position sensor 1/2, accelerator pedal position (APP) sensor
P1153	Engine control module (ECM) - adaptation to throttle valve	Adaptation to throttle valve incomplete/not carried out, throttle valve tight/sticking, throttle motor
P1154	Throttle motor - control	Wiring, throttle motor, throttle motor position sensor 1/2, accelerator pedal position (APP) sensor
P1155	Throttle motor - control	Wiring, throttle motor, throttle motor position sensor 1/2, accelerator pedal position (APP) sensor
P1156	Throttle motor position sensor 1 - signal	Wiring, throttle motor position sensor 1, throttle motor, mechanical fault
P1157	Throttle motor position sensor 1 - signal	Wiring, throttle motor position sensor 1, throttle motor, mechanical fault
P1158	Throttle motor position sensor 1 - signal	Wiring, throttle motor position sensor 1, throttle motor, mechanical fault
P1159	Throttle motor position sensor 1 - signal	Wiring, throttle motor position sensor 1, throttle motor, mechanical fault
P1160	Intake manifold	-
P1186	Mixture control (MC) - signal	Wiring, poor connection, incorrect fuel, heated oxygen sensor (H02S), exhaust leak, fuel pressure, injector control, EVAP canister purge valve, compression, air filter blocked, ignition system, ECM